

Oil Field Environmental Incident Summary

Incident: 20140110080411 **Date/Time of Notice:** 01/10/2014 08:00

Responsible Party: Hess Bakken Investments II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: EN-HYNEK 60-90 Bakken Facility

Field Name: ALGER

Well File #: 0

Date Incident: 1/9/2014

Time Incident: 09:00

Facility ID Number: 217378-02

County: MOUNTRAIL

Twp: 155

Rng: 93

Sec: 1

Qtr:

Location Description:

Submitted By: Stacy Zerr

Received By:

Contact Person: Stacy Zerr
1501 MCKINNEY
HOUSTON, TX 77010

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	110	barrels	50	barrels	50	barrels
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received: 6/24/2014

Clean Up Concluded: 5/29/2014

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

Spill was contained inside the dike and standing fluids were sucked up.

Wastes Disposal Location: Clean Harbors

Agencies Involved:

Updates

Date: 1/10/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to valve/piping leak, is reported to remain within the diking. However, as of time of report, 60 bbls remain unrecovered. Need to follow up and determine containment and lack of recovery. Roberts contacted O&G Field Coordinator for the area. He has not, so far, received a call from the company contact.

Date: 1/23/2014 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

1/23/2014 at 17:29, on location. Heavy staining within secondary containment and on tank battery. Wellpad impacted to east of tank battery, there are currently multiple piles of impacted snow and dirt, all but one of the piles have a berm of snow around them. No noticeable staining on wellpad fence along SE side or in field on other side, wellpad area between tank battery and fence has been scraped.